




x1



x2




x2



x1



x1





x4-x8






x4

30
kg




1



A diagram of a machine with a warning symbol. The machine has a vertical component on the left and a horizontal component on the right. A dashed circle highlights the junction between the two components. An arrow points from this circle to a warning triangle containing an exclamation mark.



min. 16mm



#2.5

