








t [mm]	16	18	19	22
y [mm]	0	1	4	
t [in]	5/8	11/16	3/4	7/8
y [in]	0	1/16	3/16	

4 - 11
[2 1/16 - 7/16]



t [mm]	> 22
y [mm]	t - 9
t [in]	> 7/8
y [in]	t - 3/8



4 - 11
[2 1/16 - 7/16]

1




2








3




4




5




6




7




8




9




10




11



12



13



14

