

x1

 x^2 x^2

x1

x1


A




x8

45
kg



1




t [mm]	16	>16
y [mm]	0	$t-16$




2



3



4



5

